

CEN003 - EXPERT PADDED JACKET

	MEASURING POINTS IN INCHES	XS		S		M		L		XL		XXL		3XL	TOLERANCE
	GARMENT MEASUREMENTS														
A	FULL CHEST CIRCUMFERENCE (2" below armhole)	43		45		47		50		53		56		59	0,5
D	CB LENGTH	31		31		32		32		33		33		34	0,5
H	SLEEVE LENGTH (from neck point to end of cuff)	4,5		5		5,5		6		6,5		7		7,5	0,25